

Type of Surface	N
Smooth, impervious surface	0.02
Smooth, bare, packed soil	0.10
Poor grass, cultivated row crops or moderately rough, bare surface	0.20
Deciduous timberland	0.60
Pasture or overage grass	0.40
Conifer timberland, deciduous timberland with deep forest litter or dense grass	0.80

VALUES OF N FOR KERBY'S FORMULA

Figure 29-7C